
DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: <u>SF/ALA</u> Rte: <u>80</u> PM: <u>13.2/13.9</u>

File #: 6<u>9.yy</u>

DAILY PROJECT JOURNAL

Prime Contractor: American Bridge/Fluor Enterprises, a JV Report No: DPJ-000002 **Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island Dated: 15-Nov-2006

Location: Shanghai, China

Submittals(New / Total): CWR's: 0/0 HSR's: 0/0 NCR's: 0/0		
Item	Title	Detail
1	Major component movement	Conducted Mechanical Tests on the following PQR:
		3G FCAW Min HI (HP-2006106) - initial testing all passed (Charpy impact
		at FCM (SPCM) temperature)
		1F SAW Fillet Soundness (HP-2006114) - sample etched, ZPMC did not
		measure - will size tomorrow
2	Key conversations	Caltrans explained to ZPMC Testing Center Director Mr. Liu Liu that
		typically the macro-etch specimen should also be scribed at the planar
		intersection points of the weld and measured for size to determine the
		maximum single pass and minimum multiple pass fillet weld qualified.
		ZPMC's Project Manager Mr. Chen Bin informed Caltrans that, since they
		did not get range of parameters qualified for the FCAW they wanted, they
		intend to switch to a different FCAW electrode (Hyundai Supercored 71H)
		Mr. Bin stated they would practice with the new wire during the week of
		November 20th through 24th and would like to begin testing of the new
		PQR's starting on November 28th. Mr. Bin also stated they should have the
		HPS 485 material by the end of November and would like to begin
		qualification of PQR's using this material after the PQR's for A709 gr. 345
		are complete.
3	Quality Assurance Inspectors per shift	t 2 AM
		0 PM
4	Logistics	New shop facilities still under construction. No structures have been built
		this time.
Inspected By: McClary,David		Quality Assurance Inspector
Reviewed By: Lowry, Patrick		QA Reviewer